Approved For Release 2000/08/21 : CIA-RDP78-06505A000100050188-9

a Jul 1963

MEMORANDUM FOR: Chief, Utilities Engineering Branch,

Real Estate and Construction Division, OL

SUBJECT

: Requirement for Diesel Engineer or Mechanic

on FE Area Engineer's Staff

REFERENCE

: A. Memorandum from Chief, UEB/RECD/OL to Chief,

numbered: OL 3-3281, dated

2 May 1963.

dated 5 April 1963.

25X1A

25X1A

25X1A

25X1A

Materiel personnel, who are familiar with the diesel engine maintenance problem that exists at various overseas installations, concur with the recommendation presented by the FE Area Engineer in paragraph 5 of reference B. As he stated, the service calls for assistance have increased beyond the capability of the Station diesel mechanics to handle. As a result the operating efficiency of all diesel equipment in the area has deteriorated.

25X1A 25X1A

25X1A

25X1A

In answer to the questions contained in paragraph 2 of reference A, we cannot foresee any problems of a security nature. The diesel engineer would have the same freedom of movement enjoyed The number of days he would , as well as the number of times he would have to spend at have to visit the site, depends upon the condition and the operating hours of the equipment.

An important factor to consider in determining the practicability of having a roving diesel engineer available is the inability to secure experienced, qualified technicians from local commercial sources. The only recourse has been to solicit aid from the work of the personnel have been doing a creditable job, must be recognized that their general knowledge does not provide the specialized skills needed to perform other than routine maintenance.

25X1C

25X1A

Approved For Release 2000/08/21 RDP78-06505A00010005**b**≉®

declassification